1

STEP ONE

Open attachments. Print in color. Battery border must be RED





2

STEP TWO

Once a heavy duty box is obtained (recommended size box 14x10x12), get it ready prior to packaging the battery due to it's weight. Cut the stickers, place stickers on each side of the box.









3

STEP THREE

Sign and date the battery safety document. Do not edit or change the information.



parkage that his inspected by departing and may only for regarded if they are what and greatested against short crowds.

- For more information about the bettering construents that parkage, and the labellance qualification resource.

905-670-4010. LST 254- Canada

List information countries have, recording pres crobs and any applicable country cross

Name (Mathewal of Arigans — Xemodex Inc.


6150 Kennedy Rd - Unit #7
Mississauga , on Canada

Separt X May. 2.2023

4

STEP FOUR

Print your shipping labels and the commercial invoices. Date and sign them.



5

STEP FIVE

Print your faulty symptoms report. Fill out the form.



6


STEP SIX

Pack your battery carefully to avoid any damage. Peanuts/Bubble wrap should be used.

7

STEP SEVEN

Besides the battery, the only document that goes inside is the faulty symptoms.



8

STEP EIGHT

Close/Seal your box.

9

STEP NINE

Stick the safety battery document on the top of the box.



10

STEP TEN

Place the UPS label + 3 commercial invoices in a clear plastic pouch and stick it onto the box. If you do not have a clear plastic pouch, UPS can provide you with one at the UPS store.



11

STEP ELEVEN

Finished product picture. Your battery is ready to be shipped!

